









NR.25

 S02	3.5x16 x52	 S11	M4x22 x8	 C01	x14	 C10	x22	 C11	x22	 P01	x4
 B01	x4	 M01	x4	 S01	x6	 G01	x2				



3.

C10

4.



C10

4xC10

5.

C11

C11

C11

C11

6.

C10

C10

S02

S02

G01-b

4xC11

2xC10
2xG01-b
4xS02

7.

1xD01
2xS01

S01

D01

8.

S02

B01

S02

S11


S11

B01

M01


M01

2xM01
4xS11
8xS02
4xB01




8xS02

10




11

X 2




16xS02
4xP01

12. X 2




4xC11
4xC01

13. X 2



1xD01
2xS01



2xG01-a
6xS02

14. X 2

C10

S11

C10

4xC10
1xM01
2xS11





M01




16



15. X 2

NR.110

 S02 x54	 S11 x4	 C01 x12	 S21 x12	 C10 x20	 C11 x20
 B01 x4	 M01 x2	 P01 x4	 A01 x4		



I. 2

C11

C11

C

C11

C

C11

X3


4 x C11

I. 3



I. 4

S02




S02

S02

6xS02

I. 5

drill bit 5 mm



D

S02

B01

4 x S02
2 x B01

I. 6

S02

S11

D

1 x M01
2 x S11

M01

4 x S02

II. 1

S02

A

A01

C10

C01

B

S21

S21

C10

A


S02

C01

C10

A01

4xS02
2xA01
4xC01
8xC10
8xS21



II. 2

C11

C11

C

C11

C

C11

X2

4 x C11

II. 3



II. 4

S02

S02

S02

P01

4xP01
22xS02

II. 5

D



drill bit 5 mm

S02

B01

1 x M01
4 x S02
2 x B01
2 x S11

M01

B01

D

S11

S02

II. 6

E

S02

4 x S02

E


S02

II. 7

I

II












HEIGHT ADJUSTMENT

SIDE ADJUSTMENT


DEPTH ADJUSTMENT

NR.1

 S01 7x50 x6	 S02 3.5x16 x8	 S11 M4x22 x2	 C01 x12	 D01 x1	 S21 x8
 B01 x2	 M01 x1	 A04 x2	 D04 x1		




1.



8xC01
8xS21
2xB02
4xS02

2.



2xA04
4xC01

