


NR.5

 3.5x16 S02 x32	 M4x22 S11 x4	 C01 x8	 C10 x8	 C11 x8	 P01 x4
 M01 x2					


1. C11 C10 A C11 C10 C10 C10 C10 C10 2xC11 6xC10	2. C11 C11 C01 C11 B C01 6xC11 6xC01 A C11 B C10

3.




2xC10
2xC01

4.




5.




4xB01
2xM01
4xS11
8xS02

6.






8xS02




7.



4xP01
16xS02

NR.110

 S02	 S11	 C01	 S21	 C10	 C11
3.5x16 x54	M4x22 x4	x12	x12	x20	x20
 B01	 M01	 P01	 A01		
x4	x2	x4	x4		



I. 2

C11

C11

C

C

C11

C11

X3


4 x C11

I. 3



I. 4

S02




S02

S02

6xS02

I. 5

drill bit 5 mm



D

S02

B01

4 x S02
2 x B01

S11

D

M01

1 x M01
2 x S11

I. 6

S02

4 x S02

II. 1

S02

A

A01

C10

C01

B

S21

S21

C10


A

S02

C01

C10

A01



4xS02
2xA01
4xC01
8xC10
8xS21

II. 2

C11

C11

C

C11

C

C11

X2

4 x C11

II. 3



II. 4

S02

S02

S02

P01

4xP01
22xS02

II. 5

D



drill bit 5 mm

S02

B01

1 x M01
4 x S02
2 x B01
2 x S11

M01

B01

D

S11

S02

II. 6

E

S02

4 x S02

E


S02

II. 7

I

II











HEIGHT ADJUSTMENT

SIDE ADJUSTMENT


DEPTH ADJUSTMENT

NR.1

 7x50 S01	 3.5x16 S02	 M4x22 S11	 C01	 D01	 S21
x6	x8	x2	x12	x1	x8
 B01	 M01	 A04	 D04		
x2	x1	x2	x1		




1.



8xC01
8xS21
2xB02
4xS02

2.



2xA04
4xC01

